



"Georgian Water and Power"

MARNEULI DIRRECTION PUMPING AREA

ASSESSING HEALTH AND SAFETY CONDITIONS IN FACILITIES AND WORK AREAS AND PLANNING IMPROVEMENT MEASURES


DOCUMENT PREPARED BY: SHORENA KIKNADZE
(OCCUPATIONAL SAFETY SPECIALIST)

PERSONS RESPONSIBLE FOR IMPLEMENTATION:
ALEXANDER MAGHRADZE
ARIZ GARAEV

16.09.2025

„ჯორჯიან უოთერ ენდ ფაუერი“

#	ლონისძიება	ფოტო	ქმედება
---	------------	------	---------

<p>Finding: The floor in the pump room is uneven, with multiple openings that could cause an employee or other person to trip, fall into the opening, and sustain injuries.</p> <p>The infrastructure is completely inappropriate for the work space</p>		<p>The floor of the working space must not be slippery, have a dangerous uneven surface, and must be solid, without holes, slopes and protrusions.</p> <p>(Government of Georgia Resolution No. 341 July 1, 2022. Article 5. P.2.)</p> <p>Openings (wells, pits, stairwells, any place where a person may fall) must be covered with special covers and/or sheets.</p>
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------



Resolution #477
October 27, 2017,
Article 15

„ჯორჯიან უოთერ ენდ ფაუერი“



„ჯორჯიან უოთერ ენდ ფაუერი“



„ჯორჯიან უოთერ ენდ ფაუერი“

Discovery:

The windows of the pump house have broken glass, which, if they fall, could cause physical injury to the employee and another person; it could also cause a malfunction of the climate control.



Restore damaged windows

„ჯორჯიან უოთერ ენდ ფაუერი“

Discovery:

Electrical equipment and wiring are not up to standard, there are exposed wires, they are not installed in cable channels, which can cause a fire. Voltage transfer



Electrical equipment and wiring must be designed and installed in compliance with the relevant regulatory norms so that the working space is adequately protected from fire and explosion hazards.

(Resolution of the Government of Georgia No. 341 July 1, 2022. Article 3. P.1.

„ჯორჯიან უოთერ ენდ ფაუერი“

Discovery: The electrical utility point (high voltage) is in a completely unprotected area, there is no separate room, it is not fenced and locked. Virtually all visitors can get close to the cabinets.

There are no warning signs and the doors are open



Arrange according to the standard, no other person is allowed in the territory except the authorized person.

„ჯორჯიან უოთერ ენდ ფაუერი“



„ჯორჯიან უოთერ ენდ ფაუერი“

The employee's workspace is inappropriate in terms of ergonomics.




The employee's space should be furnished according to the standard, it needs renovation.

„ჯორჯიან უოთერ ენდ ფაუერი“



„ჯორჯიან უოთერ ენდ ფაუერი“

They will use a prohibited heater for household needs.



A dining area with a bathroom and appropriate safety equipment should be provided.

The heater in question should be removed from service immediately.

„ჯორჯიან უოთერ ენდ ფაუერი“

Discovery:

There are no toilets in/near the Satumbo area.



1. The required number of toilets must be located near the workplace, rest and changing rooms, showers, and washbasins.
2. Toilets must be equipped with an exhaust fan or ventilation system and washbasins.

(Resolution of the Government of Georgia No. 341 of July 1, 2022. Article 18. P.1; P.4.